


Good practices in the Green Office tutoring process

Good practice title	Natural light through roof windows
Good practice photo(s)	
Name of Office	Energypartner OÜ
Type of Office (sector)	Consulting – energy solutions, ventilation, energy audit etc
Website	www.energiapartner.ee
Country	Estonia
Tutor name	Karin Kilk
Environmental aspect/management aspect	Energy, IT equipment
Description of good practice (max 250 characters), including the aim of the activity; indicator(s); used measures and tools; results and achievements; communication	<p>Energypartner OÜ new office has roof windows thanks to which part of the office has less need for artificial lighting.</p> <p>Due to roof windows the energy consumption for lighting is smaller.</p>

related activities.	
Cost/payback period	-
Challenges in implementation	Since there has not been any specific measurements done, it is questionable whether the energy consumption will be reduced by less need for lighting or will it on the contrary be increased since the heat losses are bigger through a window than through a roof.
Replicability (yes/no)	